

Nickel-Based Alloy Recommended for Cast Iron Protection and Repair

Eutalloy[®] 10680



COATING

- Deposits are easily machinable and porous-free
- Compressive strength resists deformation at high temperatures
- No deposition scaling with increased temperatures
- Precise deposition with minimal overspray



DESCRIPTION:

Eutalloy 10680 is a premium nickel base alloy powder designed to provide easy build-up on cast iron parts and excellent machinability. Machined deposits are bright and porosity free. The hardness of this alloy promotes good edge integrity while not detracting from its machinability. The high compressive strength of this alloy resists deformation at elevated temperatures. Deposits will not scale even at elevated temperatures. The Eutalloy process permits precise deposition with a minimal amount of overspray. Thin, tough overlays can be applied and dimensional tolerances maintained.

TECHNICAL DATA:

Powder Properties

Nominal Composition: Nickel, Boron, Silicon

Hall Flow Rate: 14 seconds

Bulk Density: 4.8 g/cc

Coating Properties

Typical Tensile Shear Strength: 75,000 psi

Typical Hardness: HRB 95

Maximum Service Temperature: 1200°F (649° C)

Thickness Limit: Unlimited

APPLICATIONS:

General-purpose build-up and dimensional restoration for cast iron and steel parts such as:

- Gears Shafts
- Patterns
- Clutches
- Templates

EQUIPMENT:

Eutalloy 10680 may be applied by either the Eutalloy B torch or the UltraJet Eutalloy torch using acetylene as the fuel gas.

PROCEDURE FOR USE:

Preparation:

All surfaces to be coated should be thoroughly cleaned, removing all contaminants, oxides and grease. Thin surfaces and edges require no preheating. However, large, heavy and cast iron parts of all thickness should be heated to about 575°F (approx. 302°C) (blue hot).

Coating instructions:

For coating operations the flame of the Eutalloy B or SuperJet S torch should be adjusted to neutral with the powder feed on. To prevent oxidation of the base material we recommend spraying a thin coat of Eutalloy 10224. A second coat is delivered in the following manner: preheat locally to fusion point (when the first coat becomes glazed in appearance), then spray and fuse the second coat simultaneously. Move progressively along, spraying and fusing, until the entire surface is covered. Distance between the cone of the flame and the piece should be .25 - .75 inch. Leave the part to cool slowly and away from air currents. Where possible, place it in vermiculite or cover with a thermal blanket

YOUR RESOURCE FOR PROTECTION, REPAIR AND JOINING SOLUTIONS



EUTECTIC CORPORATION

N94 W14355 Garwin Mace Drive
Menomonee Falls, WI 53051 USA
Tel.: +1 (800) 558-8524
eutectic.com

EUTECTIC CANADA

428, rue Aimé-Vincent
Vaudreuil-Dorion, Québec
J7V 5V5 Canada
Tel.: +1 (800) 361-9439
eutectic.ca

