

High Strength and Ductility under Tough Conditions

Xuper[®] 2222 XHD



WELDING

- For use with flame-hardening equipment
- Formulated for high speed welding of critically stressed applications
- Excellent for high temperature and sub-zero cryogenic applications



DESCRIPTION

Xuper 2222XHD is a nickel-based electrode formulated for high-speed, high-deposition welding of critically stressed applications. Deposits exhibit superior crack resistance and ductility. This easily handled electrode is ideal for welding large cross sections in a variety of steels where cool-down stresses can be a problem. Xuper 2222XHD maintains a high-tensile strength at high temperatures (1200°F) as well as in cryogenic applications.

WELDING PROCEDURE & TECHNIQUE

Preparation: Remove all contaminants, particularly oil and grease. Lightly grind surface to remove superficial oxides. Preheating is not necessary unless the part has a large cross-section or has high air hardenability. In these situations preheating within a range of 250-300°F is advised.

Technique: Always use the lowest practical amperage range to minimize dilution. Use a medium-to-short arc length and stringer-beads. Terminate welds either on end-blocks and back-whip or use a "side-up technique". Adopt a balanced welding sequence to minimize base metal over-heating. De-slag thoroughly.

Post-Welding: For air-hardening steels, slow cool using available insulating materials. For less-sensitive metals, slow cool out of drafts.

TYPICAL ANTI-WEAR APPLICATIONS & INDUSTRIES

APPLICATIONS

- Heat-Treating Trays & Baskets
- Ingot Tongs
- Continuous Casting Molds
- Merchant Mill Roll Guides
- LNG Processing Pumps

INDUSTRY

- Forging
- Iron and Steel Works
- Casting of Metals
- Iron and Steel Works
- Liquefied Natural Gas Plants

XUPER 2222XHD TECHNICAL DATA & SET-UP INFORMATION

Typical Tensile Strength: 90,000 psi (620 N/mm²)

Typical Yield Strength: 65,000 psi (450 N/mm²)

Typical Elongation (1=5d) min.: 42%

Typical Hardness: BHN: 180

Diameter [mm] / [in.]		Amperage [A] Range
2.4	3/32	80 - 120
3.2	1/8	110 - 160
4.0	5/32	150 - 190

Note: When welding with Xuper 2222XHD make sure to remove ALL sources of sulfur, often an ingredient in both oils and greases.

YOUR RESOURCE FOR PROTECTION, REPAIR AND JOINING SOLUTIONS



Eutectic Corporation
N94 W14355 Garwin Mace Drive
Menomonee Falls, WI 53051 USA
P 800-558-8524 • F 262-255-5542
www.eutectic.com

Eutectic Services
12300 Carmen Avenue
Milwaukee, WI 53225 USA
P 800-558-8524 • F 262-255-5542



Statement of Liability: Due to variations inherent in specific applications, the technical information contained herein, including any information as to suggested product applications or results, is presented without representation or warranty, expressed or implied. Without limitation, there are no warranties of merchantability or of fitness for a particular purpose. Each process and application must be fully evaluated by the user in all respects, including suitability, compliance with applicable law and non-infringement of the rights of others, and Eutectic Corporation and its affiliates shall have no liability in respect thereof.

2222XHD 09-15 © 2008, Eutectic Corporation, ® Reg. T.M., Printed in the U.S.A.