

Nickel-Based Alloy Recommended for Cast Iron Protection and Repair

Eutalloy® 1206

• Ideal for protective coating, joining and cladding applications

- The deposit is easy to machine with standard cutting tools
- Exceptionally heat resistant
- Ideal for protection against metal-to-metal friction

Eutalloy 1206

Eutalloy 1206 is a nickel-based alloy with properties which make it ideal for protective coating, joining and cladding applications on a variety of base metals including steels, cast irons and nickel alloys. The deposit is easy to machine, with standard cutting tools, and has a low coefficient of friction and wear resistance properties which make it ideal for protection against metal-to-metal friction on glass molds. It is also exceptionally heat resistant.

Eutalloy 1206 is manufactured by a process of atomization, designed to ensure both optimum spheroidization and controlled granulometry. This in turn ensures trouble-free fusion of the alloy using our SuperJet-S Eutalloy torch. Eutalloy1206, applied with Eutalloy system, produces smooth and uniform quality coatings.

This maintenance-engineered coating technology increases the value and reliability of parts treated, with results far superior to conventional repair processes, and savings in costs including those of machining.

Eutalloy 1206 is recommended for rectifying both machining and casting defects on glass molds, as well as for protective coatings against oxidation, with a considerable gain in service life for a number of parts.

TECHNICAL DATA

90 HRB
1920 - 2330°F (1049 - 1277°C)
0.293 lb./in ³
1112°F (600°C)
Excellent
Very Good
Excellent, with normal cutting tools
Recommended for steels, cast irons, and nickels
SuperJet S

PROCEDURE FOR USE

Preparation: All surfaces to be coated should be thoroughly cleaned, removing all contaminants, oxides and grease. Thin surfaces and edges require no preheating. However, large, heavy and cast iron parts of all thicknesses should be heated to approx. 575°F (approx. 302°C) (blue hot).

Coating Instructions: For coating operations the flame of the SuperJet S torch should be adjusted to neutral with the powder feed on. To prevent oxidation of the base material we recommend spraying a thin coat of Eutalloy 1206. A second coat is delivered in the following manner: preheat locally to fusion point (when the first coat becomes glazed in appearance), then spray and fuse the second coat simultaneously. Move progressively along, spraying and fusing, until the entire surface is covered. Distance between the cone of the flame and the piece should be 0.25 - 0.75 inch. Leave the part to cool slowly and away from air currents. Where possible, place it in vermiculite or cover with a thermal blanket.

TYPICAL APPLICATIONS

e Recommended for corrosion/wear-resistant coatings on glass molds as well as journals, gearwheels and exhaust manifolds. Also, for repair of casting and machining defects and for repair of worn areas of deep-drawing dies.



Eutectic Corporation: N94 W14355 Garwin Mace Dr. Menomonee Falls WI, 53051 USA +1 800. 558. 8524 • eutectic.com *Eutectic Canada:* 428, rue Aimé-Vincent Vaudreuil-Dorion

Québec J7V 5V5 Canada +1 800. 361. 9439 • eutectic.ca



Observe normal spraying practices, respiratory protection and proper air flow pattern advised. For general spray practices, see AWS Publications AWS C2. 1-73, "Recommended Safe Practices for Thermal Spraying and AWS TSS-85, "Thermal Spraying, Practice, Theory and Application." Thermal spraying is a completely safe process when performed in accordance with proper safety measures. Become familiar with local safety regulations before starting spray operations. DO NOT operate your spraying equipment or use the spray material supplied, before you have thoroughly read the equipment instruction manual. Refer to the Eutectic website for Material Safety Data Sheet (MSDS) information. DISREGARDING THESE INSTRUCTIONS MAY BE HAZARDOUS TO YOUR HEALTH.

